

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD



April 10, 2013 **View east at former corral area of former B & B Dairy. Illegal disposal of manure at northwest area of calf operation on GH Dairy #1. Calf operation is at east end of facility.**



April 10, 2013 View east at former corral area of former B & B Dairy. Illegal disposal of manure at northwest area of calf operation. GH Dairy #1 calf operation at upper right. Calf operation is at east end of facility.



April 10, 2013 View south at former corral area of B & B Dairy. Illegal disposal of manure at northwest area of calf operation for GH Dairy #1. Calf operation is at east end of facility.



April 10, 2013

View west at illegal disposal of manure in Evap Basin #1 at southeast area of GH Dairy #1.



April 10, 2013

View south at illegal disposal of manure in Evap Basin #2 at southeast area of GH Dairy #1.



April 10, 2013

View southwest at illegal disposal of manure in Evap Basin #1 at southeast area of GH Dairy #1.



April 10, 2013

View west at illegal disposal of manure in Evap Basin #1 at southeast area of GH Dairy #1.



April 10, 2013 View west at illegal disposal of manure in Evap Basin #2 (on right), at southeast area of GH Dairy #1. Basin at left half of photo is not shown on EWMP site plan.